



Taterloch

Tătărlăua / Felsötatárlaka

Alba County

Built	1912
Opus	21
Organ builder	Carl EINSCHENK
Key action	pneumatische Kegellade
Stop action	pneumatisch



verschmutzt

Position in the church

Westempore / balconul vestic

Case and console

Neugotisch, 3 Felder, wenige vergoldete Verzierungen auf grauem Grund, Zinkpfeifen; Spieltisch zur Orgel. /
Neogotic, 3 câmpuri, decente ornamente aurii pe fond gri, tuburi de zinc; consola cu fața spre orgă.

Stop list

Manual 1 Bourdon 16', Geigenprincipal 8', Lieblich Gedackt 8', Octave 4', Superoctav 2'.

Pedal Subbafs 16'.

PK, Super OK. Multiplex / Sistem multiplex

Condition

Unspielbar: Balg kaputt, Pfeifen voller Schutt, schwache Pfeifenqualität im Inneren (Subbafs 16'). / Impracticabil:
tuburi umplute cu moloz, calitate inferioară a unor tuburi din interior (Subbafs 16').

Miscellaneous

Kein Orgelmotor.

Literature

– Binder, Hermann: Orgeln in Siebenbürgen (Orga în Ardeal – Irineu Buga) GMV. D-55481 Kludenbach, 2000

More photos



verwahrlost



Prospekt