



Marienburg bei Schäßburg

Hetiur / Hétur

Mureș County

Built	1850
Organ builder	Samuel Friedrich BINDER
Key action	mechanisch
Stop action	mechanisch



Altar und Orgel

Repairs and restorations ■■■

1873 Friedrich Binder

1904 Karl Einschenk;

Position in the church ■■■

Über dem Altar / deasupra altarului

Case and console ■■■

Mit geometrischen Verzierungen, bunt bemalt, 5 Felder, Zinkpfeifen. / Cu ornamente geometrice, viu colorat, cinci câmpuri de tuburi din zinc.

Stop list ■■■

Manual 1 Principal 8', Gedackt 8', Octave 4', Flöte 4', Salicional 4', Octave 2', Mixtur 3-4 fach.


Condition ■■■

Unspielbar, Traktur von Nagetieren zerfressen. / Instrument cu mecanica deteriorată de rozătoare.

Literature ■■■

- Binder, Hermann: Orgeln in Siebenbürgen (Orga în Ardeal – Irineu Buga) GMV. D-55481 Kludenbach, 2000
- Dávid, István: Műemlek orgonak Erdélyben (Orgi, monumente istorice din Transilvania), Editura Polis Balasi, Cluj Napoca, Budapesta, 1996

More photos ■■■



Marder am Werk