



Kelling

Câlnic / Kelnek

Alba County

Built	1867
Organ builder	Carl HESSE
Key action	mecanică
Stop action	mecanică



Repairs and restorations ■■■

1924 repariert durch Karl Einschenk

2007/2008 repariert von Papp Zoltan

Position in the church ■■■

Westempore / balconul vestic al bisericii

Case and console ■■■

Neugotisch, 5 Felder, holzfarben mit vergoldeten verzierungen, Pfeifen nicht original. / Neogotic, lemn și ornamente aurite, cinci câmpuri cu tuburi neoriginale.

Inscriptions ■■■

über der Klaviatur / deasupra claviaturii: CARL HESSE IN WIEN

Stop list ■■■

Manual 1	Principal 8' (pneumatisch gesteuert), Flauto 8', Viola 8', Octav 4', Flauto 2 2/3', Superoctav 2', Quinte 1 1/3', Octavin 1',
Pedal	Subbafs 16', Principalbafs 8':
PK, OK.	

Condition ■■■

Trotz Reparatur fehlerhafter Zustand. / Reparat, totuși prezintă defectiuni.

Miscellaneous ■■■

1978 Orgelventilator eingebaut.


Literature ■■■

- Binder, Hermann: Orgeln in Siebenbürgen (Orga în Ardeal – Irineu Buga) GMV. D-55481 Kludenbach, 2000
- Dávid, István: Műemlek orgonak Erdélyben (Orgi, monumente istorice din Transilvania), Editura Polis Balasi, Cluj Napoca, Budapesta, 1996

More photos ■■■



Firmenschild



Traktur bei Hesse