



Durles

Dârlos / Darlac

Hermannstadt / Sibiu County

Built	1841
Organ builder	Friedrich und Wilhelm MAETZ
Key action	mechanisch
Stop action	mechanisch



Repairs and restorations ■■■

1896 Reparatur durch Max Herbert

1910 Leopold Wegenstein

Position in the church ■■■

Westempore / balconul vestic al bisericii

Case and console ■■■

Klassizistisch, 7 Felder, Zinkpfeifen, grüne und goldene Blumenornamente. / Clasicist, 7 câmpuri, tuburi de zinc neoriginale, cu ornamente florale verzi și aurii.

Stop list ■■■

Manual 1 Principal 8', Gedackt 8', Viola 4', Flauta 4', Octav 2', Quinte 2 2/3', Mixtur 3 fach, Bourdon 16',.

Condition ■■■

Traktur von Nagetieren zerfressen, Balg beschädigt. / tractura deteriorată de rozătoare, burduful spart.

Literature ■■■

- Binder, Hermann: Orgeln in Siebenbürgen (Orga în Ardeal – Irineu Buga) GMV. D-55481 Kludenbach, 2000
- Dávid, István: Műemlek orgonak Erdélyben (Orgi, monumente istorice din Transilvania), Editura Polis Balasi, Cluj Napoca, Budapesta, 1996

More photos ■■■



Marder am Werk



Spieltisch