



Kleinalisch

Seleuş / Szászsöllös

Mureş County

Built	1830
Organ builder	Samuel Joseph MAETZ
Key action	mechanisch
Stop action	mechanisch



Zustand 2010

Repairs and restorations ■■■

1904 Karl Einschenk

1930 Wegenstein

1961 Otto Einschenk.

Position in the church ■■■

Westempore / balconul de vest

Case and console ■■■

Klassizistisch, 7 Felder, vergoldete Blumenornamente, Prospektpfeifen aus Zink; Spieltisch zum Altar. / Clasicist, 7 câmpuri, ornamente florale aurii, tuburi de prospect din zinc; consola întoarsă cu fața spre altar.

Inscriptions ■■■

Täfelchen über dem Manual / tăbliță deasupra manualului: Karl Einschenk renovirt 1904

Stop list ■■■

Manual 1 Coppel 8', Principal 4', Flöte 4', Gambe 4', (war Octav 2'), Quint 1 1/3', Mixtur 3 fach.

Condition ■■■

Nicht spielbar, vom Holzwurm befallen / Impracticabil, carcasa atacată de carii de lemn.

Miscellaneous ■■■

Kein Orgelventilator, nur Tretbalg.

More photos ■■■



Prospekt



Mechanik 2010